



No	Phone	Type	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
1	Motorola	V80	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R37_G_0E.05.26R	
2		V500	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.08.8F5R	
3		V525	HF	✓	✓					✓	✓	✓	✓	/ TRIPLETS_G_0B.09.1DR_VA	
4		V550	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.26R	
5		V551	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R47_G_08.17.0FR_01	
6		V557	HF	✓	✓					✓		✓		/ R4512_G_08.28.40R	
7		V600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.09.38R
8		V620	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.25R
9		V635	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R474_G_08.48.24R_A
10		L2	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.53.15R
11		L6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.50.22R
12		L7	HF	✓	✓	✓				✓	✓	✓	✓	✓	/ R4513_G_08.B7.5DR_RB
13		V3	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R374_G_0E.40.79R
14		V3c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R479_G_08.B4.85R
15		V3i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R479_G_08.B4.85R
16		V3xx	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 26111LD_U_96.80.56R
17		K1	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R4527_G08.22.07R
18		K1mm	HF	✓	✓		✓	✓		✓	✓				/ 24.5_01.09.HA
19		L7cm	HF	✓	✓		✓	✓		✓	✓				/ 24.5_01.11.HA
20		U6	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R478_G_08.83.76R_A
21		C390	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R368_G_0B.A0.0FR
22		Z3	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R4527_G08.01.02R
23		1070	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R25221LD_U_85.97.C3P
24		ROKR E1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R373_G_0E.30.42R
25		E550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.14R_A
26		E770v	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221_U_85.83.E1P
27		E815	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ E815_X_01.21.0R_HA
28		E1000	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R478.G_08.83.76R_A
29	Nokia	3109c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ V cp06w15_07w15	
30		3110c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ Vp sk4.80
31		3230	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.0505.2
32		3250	HF	✓	✓										/ 3.24
33		5200	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.25
34		5300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.92
35		5500d	HF	✓	✓										/ 4.03
36		5700	HF	✓	✓						✓	✓	✓	✓	/ 03.27
37		6021	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 04.90
38		6085	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.71
39		6103	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 04.90
40		6111	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 03.58
41		6125	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 03.71
42		6131	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 3.70
43		6151	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 3.56
44		6230	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 05.24
45		6230i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.88
46		6233	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.70
47		6234	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.91
48		6270	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.66
49		6280	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 3.65
50		6288	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 5.92
51		6300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	v04.70
52		6310	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 4.10
53		6310i	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 5.60
54		6600	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.42.1
55		6630	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 2.39.152
56		6670	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 6.0522.0
57		6680	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	✓	/ 2.04.15
58		6681	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.10.6
59		6682	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.01.1
60		6820a	HF	✓	✓						✓	✓	✓	✓	/ 4.25
61		6822a	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.52

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)



No	Phone	Type	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
62	Nokia	7280	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 3.22	
63		7710	HF	✓	✓						✓	✓	✓	/ 3.04.2	
64		8800	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 4.10	
65		8801	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 3.94	
66		8910	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 04.02.25	
67		9300	HF	✓	✓						✓	✓	✓	/ 5.22	
68		9300i	HF	✓	✓						✓	✓	✓	/ 5.50	
69		E50	HF	✓	✓									/ 06.41.3.0	
70		E60	HF	✓	✓									/ 2.0618.06.05	
71		E61	HF	✓	✓									/ 2.0618.06.05	
72		E65	HF	✓	✓									/ 1.0633.18.01	
73		E70	HF	✓	✓									/ 2.0618.07.10	
74		E90	HF	✓	✓							✓	✓	/ 07.24.0.3.OP	
75		N70	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	/ 5.0638.3.0.1	
76		N71	HF	✓	✓									/ 2.0613.1.12.1	
77		N73	HF	✓	✓									/ 2.0628.0.0.1	
78		N76	HF	✓	✓							✓	✓	/ 10.0.035	
79		N80-1	HF	✓	✓									/ 3.0617.0.6	
80		N90	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	/ 5.0607.7.3	
81		N91	HF	✓	✓									/ 1.11.003	
82		N93	HF	✓	✓									/ 10.0.025	
83		N93i	HF	✓	✓									/ 11.0.009	
84		Sony-Ericsson	D750i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1AA008 PRG CXC125952_EU_1_CLR1AA008
85			K510i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
86	K550i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1JA015 prg CXC1250669_GENERIC_LI
87	K600i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2AC001 CXC1250076.EU.6_MI
88	K610i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1BA022 prgCXC1250536_V
89	K700i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2L001 prgCXC 125821_EU_1_C
90	K750i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1C004 prgCXC 1250035_EU_2_CL
91	K800i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001
92	K810i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1KC001
93	M600i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1B01
94	P800		HS	✓	✓										
95	P900		HS	✓	✓										
96	P990i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4F01 CXC162058
97	S700i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3C002 PRGCXC125936_EU_2_T
98	T610i		HF	✓	✓						✓	✓	✓	✓	/ R3C002
99	T630i		HF	✓	✓						✓	✓	✓	✓	/ R7A011
100	V630i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1CE001
101	V800		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ P1J002 prg CXC125839_EU_1_VA
102	W550i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4BA041
103	W600i		HF	✓	✓						✓	✓	✓	✓	/ R7B046
104	W800i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1L002 PRG CXC1250092_EU_1_CA R1L002
105	W810i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4DB005 prg CXC1250320
106	W850i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001 PRGCXC1250201_Vodafone_CYR1E
107	W880i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1JC002
108	W900i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R5BC004
109	W950i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R9C001 prg CXC162037
110	Z530i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R6BA030 PRG 1250454_GENERIC_MUR6BA030
111	Z600		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2E004 CXC125731_EU_7
112	Z610i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001
113	Z1010		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1G007 PRG CXC125432_EU_1_V

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)



No	Phone	Type	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
114	Siemens	CX75	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓		/ SW:17
115		M75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23
116		S55	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:91
117		S65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 50
118		S65v	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ SW:25
119		S75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:16
120		SK65	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ SW:50
121		SP 65	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ SW: 47
122		BenQ MB1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:46
123		BenQ S68	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23
124	Samsung	A900	HF	✓	✓			✓	✓	✓	✓	✓			/ SW: 1.0g
125		D307	HF	✓	✓			✓	✓	✓					/ 06
126		D357	HF	✓	✓	✓		✓	✓	✓		✓	✓		/ 1.4
127		D500	HF	✓	✓			✓	✓	✓					/ EG001.08
128		D520	HF	✓	✓	✓						✓	✓		/ SW: 1.0C
129		D600	HF	✓	✓										/ TG001.06
130		D840	HF	✓	✓	✓	✓	✓	✓	✓		✓	✓		/ F:Rev1.0a
131		D800	HF	✓	✓	✓		✓	✓	✓		✓	✓		/ 1.1
132		D900	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ D900E.05
133		E250	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ E250JHGB1
134		E380	HF	✓	✓	✓		✓	✓	✓		✓	✓	✓	/ FE380.02
135		E720	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ SW: 1.0g
136		E900	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 1.0a
137		i600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 5.1.342 (Build 15096.3.0.0) RV i600XAFI3
138		P900	HF	✓	✓	✓		✓	✓	✓		✓	✓		/ Rev 1.1
139		U600	HF	✓	✓	✓		✓	✓	✓		✓	✓		/ ver:REV 0.2
140		X820	HF	✓	✓	✓		✓	✓	✓		✓	✓		/ Rev. 0.3b
141		Z230	HF	✓	✓										/ Z230JHFL2
142	Z240	HF	✓	✓										/ Z240AIGC6	
143	Z370	HF	✓	✓						✓		✓		/ Z370JIGD4	
144	BlackBerry	7100	HF	✓	✓								✓		/ 4.02.16
145		7130	HF	✓	✓										/ 4.10.327
146		8100	HF	✓	✓		✓				✓	✓	✓		/ 4.2.0.51 (Platform 2.2.0.32)
147		8707	HF	✓	✓	✓					✓	✓	✓		/ 4.1.0.275
148	HTC	MDA	HF	✓	✓	✓		✓	✓	✓					
149		Xda Trion	HF	✓	✓	✓		✓	✓	✓					/ 1.25.207.1
150		TyTN	HF	✓	✓	✓		✓	✓	✓					/ 0.93.03
151	MDA II	HS	✓	✓										/ 1.72.01GER	
152	LG	KG800	HF	✓	✓										
153		KG810	HF	✓	✓										
154		KP800 (8000)	HF	✓	✓										/ PX80PC06
155	SHARP	GX15	HF	✓	✓										/ A07-0070210
156		GX25 GZ200	HF	✓	✓										
157		GX30i	HF	✓	✓										/ A02-010-0041
158	PalmOne	Treo 650	HF	✓	✓			✓	✓	✓	✓	✓	✓		/ TREO650-1.02-CNG Firmware:1.51
159		Treo 680	HF	✓	✓			✓	✓	✓	✓	✓	✓		/ TREO-680-1.00A/3102-
160		Treo 700p	HF	✓	✓			✓	✓	✓	✓	✓	✓		/ 2106/105
161		Treo 750v	HF	✓	✓			✓	✓	✓	✓	✓	✓		/ TREO750-1.14-VFD

Bury GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)